CORNER RECORD

Agency Index


Document Number ADJ 121-130-27

City of	NICASIO	County of	MADIN	
Brief Legal Description IRON PIPE SHOWN ON MA			, California S 14.	
CORNER TYPE		COORDINATES (Optional)		
	Government Meander Rancho Date of Survey	Corner Control Property Other	NElevation Units	
PLS Act Ref.:	8765(d)	× 8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
FOUR REFERENCE UCS DWG #300. (PE SHOWN ON M CE TIES; RE-ESTA SEE ATTACHED S	ABLISHED WITH CO SKETCH) NO DETE	LOT 8 AS SHOWN ON DUNTY OF MARIN WE RMINATION WAS MA ITS RELATION TO PE	ELL MONUMENT PER ADE AS TO THE
	SURVEYOR'S	STATEMENT		
This Corner Record was the Professional Land Su	rveyors' Act on	my direction in conforman		JOHN R. SEMERAD No. 9292
This Corner Record was and examined and filed Signed Title County Surveyor's County	6/20/22 Parts y Surveyo	P.L.S. OCRICOD No		TRACY W. PARK NO. 8176



A.P.N. 121-130-27 #5858 LUCAS VALLEY ROAD

LANDS OF SOARES AS SHOWN ON 7 OS 14



REF 1:

FOUND IRON PIPE AND TAG IN MONUMENT WELL STAMPED R.E. NO.8424 PER 7 OS 14 REPLACED WITH STANDARD COUNTY MONUMENT PER UNIFORM CONSTRUCTION STANDARDS DRAWING #300.

REF 2:

SET HUB AND WASHER STAMPED "MARIN COUNTY SURVEYOR" ON SHOULDER OF ROAD.

REF 3:

SET NAIL AND BRASS TAG STAMPED "MARIN PW" ON SIDE OF TREE.

RFF 4.

SET NAIL AND WASHER STAMPED "MARIN COUNTY SURVEYOR" IN ASPHALT DRIVEWAY.

REF 5: SET HUB AND WASHER STAMPED "MARIN COUNTY SURVEYOR" ON SHOULDER OF ROAD.

COUNTY OF MARIN

DEPARTMENT OF PUBLIC WORKS
SURVEY SECTION

SCALE: 1"=40'

3 PM 55

JOB No. 2018-026

LOTE

CORNER RECORD