CORNER RECORD

Agency Index

Documen Number ADJ 121-210-25

City of	NICASIO	County of _	MARIN	, California
Brief Legal Description 3/4" IRON PIPE SHOWN ON 7 OS 73.				
	Government Meander Rancho	Corner Control Property Other	NElevation Units	U.S. Survey Foot Ch Date Resources Code §§8801-8819 Resources Code §§8890-8902
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE SHOWN ON 7 OS 73 NEAR TRACT B . SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN STANDARD WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on P.L.S. or Re.E. No. 9292 P.L.S. or Re.E. No. 9297				
This Corner Record was and examined and filed Signed Title County Surveyor's	as received d 6/20/22 liPak nty Surv	P.L.S. PROFE NO.	8176	TRACY W. PARK NO. 8176

