CORNER RECORD

Agency Index

DRW # 19-037

City of	NICASIO	County of	MARIN	N , California
Brief Legal Description IRON PIPE SHOWN ON MAP 7 OS 14.				
	CORN Government Co Meander Rancho Date of Survey	orner X Control Property Other	NElevation Units	och Date
PLS Act Ref.:	8765(d)	× 8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND IRON PIPE SHOWN ON MAP 7 OS 14 NEAR PARCEL 8A AS SHOWN ON MAP 5 PM 61. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HEREON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT				
This Corner Record was prepared by me or under my direction in conformance with				
the Professional Land Surveyors' Act on O6/20/2 Z Signed P.L.S. or R.C.E. No. 9292 No. 9292				
This Corner Record was received COUNTY SURVEYOR'S STATEMENT This Corner Record was received				
and examined and file Signed Title County Surveyor's	1. Pal ny Surve	P.L.S. OF ROF. No.	8176	TRACY W. PARK NO. 8176 TO CALIFO OTHER OF CALIFO TRACY W. PARK NO. 8176

