## **CORNER RECORD**

Agency Index

Document Number ADJ 121-240-14

DPW # 19-638

City of	NICASIO	County of _	MARIN	, California
Brief Legal Description IRON_PIPE SHOWN ON MAP 7 OS 14.				
Brief Legal Descrip	COI  Government  Meander  Rancho	RNER TYPE	COORDINATES (Option  N E Elevation	S. Survey Foot  de §§8801-8819
PLS Act Ref.:	8765(d)	× 8771	8773 Other	:
Corner/ Monument:	Left as found Found and tagged	Established  Reestablished		onstruction Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed:  See sheet #2 for description(s):  FOUND IRON PIPE SHOWN ON MAP 7 OS 14 NEAR LOT 8 AS SHOWN ON MAP 2 PM 57. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HEREON OR ITS RELATION TO PROPERTY LINES IN THE AREA.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with				
This Corner Record was prepared by me or under my direction in conformance with  the Professional Land Surveyors' Act on  P.L.S. or B.E.E. No. 9292  COUNTY SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with  SER LAND SURVEYOR'S LAND SURVEYOR'S STATEMENT  COUNTY SURVEYOR'S STATEMENT				
This Corner Record was and examined and filed Signed Title County Surveyor's	as received Mineral Marchael M	P.L.S. GRAGGE No.	8176 * PROFESS	LAND SURPER RACY W. PARK NO. 8176  TE OF CALIFO

