


**CORNER RECORD**

Document Number 125.261.31  
City of NOVATO County of MARIN; California

Brief Legal Description LOT 93, 12 MAPS 38 & LOT 2, 5 PM 9



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey Oct. 31, 2001

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE MOST SOUTHERLY LOT CORNER  
OF LOT 93 OF 12 MAPS 38 & ALSO REESTABLISH  
ALL ANGLE POINT OF LOT 2, 5 PM 9 @ THE INTER-  
SECTION OF THE COURSES N47°26'W, 171.17' &  
N26°23'33"E, 76.33 PER 5 PM 9. REFER TO SKETCH ON P. 2

A description of the physical condition of the monument as found and as set or reset:

POINTS SET WERE REESTABLISHED FROM FOUND ORIGINAL  
CORNERS OF LOT 2, 5 PM 9 (SEE SKETCH)  
1) @ SOUTHERLY CORNER LOT 93 (12 MAPS 38) SET 1/2" REBAR W/  
PLS CAP 5379 2) AT ANGLE POINT IN LOT 2 5 PM 9, SET LEAD  
PLUG WITH LSTAG 5379 IN ASPHALT PAVING

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Nov. 2nd 2001

Signed [Signature] P.L.S or R.C.E. No. PLS 5379  
RENEWAL 6.30.2001

**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received NOVEMBER 7, 2001

and examined and filed NOVEMBER 8, 2001

Signed [Signature] P.L.S or R.C.E. No. 7128

Title DEPUTY

County Surveyor's Comment \_\_\_\_\_



Prepared by: DJ SCRANTON SURVEYING 845 Olive Ave NOVATO, CA

