


CORNER RECORD

Document Number APN 132-271-10

City of Novato

County of Marin, California

Brief Legal Description Lot 54, Unit 2, 771 St. Francis Ave., 10 RM 122.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Date of Survey 9 November 2006

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4" Iron Pipe L.S. 3049 (1) and Found Pin in Monument in Well (2) per 10 RM 122.

A description of the physical condition of the monument as found and as set or reset: _____
Set Iron Pipe and Yellow Cap R.C.E. 18221 at NW and SE corners (2).
Set Brass Tag and Tack in Wood Rail at South corner (1).
Set Mag Nail and Washer R.C.E. 18221 at SW corner (1).

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on NOVEMBER 11, 2006.

Signed [Signature] P.L.S. or R.C.E. No.: 18221



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 13, 2006 and examined and filed DECEMBER 13, 2006.

Signed [Signature] P.L.S. or R.C.E. No.: 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

