


CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3/4" I.D. iron pipe with tag "LLS 3303"; at the northeasterly corner of Parcel 'B'; "Parcel Map" recorded in Book 3 of Parcel Maps at Page 76; Marin County Records.

AP No. 132-281-14

Survey No. 1703

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED



As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

SIGNED: April 8 1988

SIGNED: LS 3775 exp. 12/31/91



COUNTY SURVEYOR'S CERTIFICATE

RECORD WAS RECEIVED 5-4 1988

AND EXAMINED AND FILED 5-5 1988

BY: DRP


TITLE: DRS

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3/4" I.D. iron pipe with tag "LLS 3303"; at the southwesterly corner of Parcel 'B'; "Parcel Map" recorded in Book 3 of Parcel Maps at Page 76; Marin County Records.

AP No. 132-281-14 Survey No. 1703

PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED



As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____


ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 SUPERVISION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 April 8 1988

SIGNED: _____
 R.C.E. No. LS 3775 exp. 12/31/88




COUNTY SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS RECEIVED 5-4 1988
 AND EXAMINED AND FILED S-S
 BY: REED P
 FILE: LEC

DOCUMENT NO. _____

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 3/4" iron pipe with plastic plug "LS 3971" at the northeasterly corner of Parcel 2; per "Parcel Map"; recorded in Book 17 of Parcel Maps at Page 68; Marin County Records.



AP No. 132-281-14 Survey No. 1703

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


As Shown

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 April 8 1988



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND FILED
 Exp. 3-31-92
 BY: [Signature] TITLE: [Signature]

SIGNED: _____
 I.S. or R.C.E. No.: LS 3775 exp. 12/31/91