


CORNER RECORD

City of Novato

Document Number 146-250-81
County of Marin, California

Brief Legal Description Lot 2 of 11 PM 51



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey November 13, 2006

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Nails in pavement on Hatch Road, per 11 PM 51.

A description of the physical condition of the monument as found and as set or reset: Set Rebar & Cap (RCE 30465) & Iron Pipe & Plug (RCE 30465), per 11 PM 51.

SURVEYOR'S STATEMENT

This corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Nov 13, 2006

Signed [Signature] P.L.S. or R.C.E. No. 30465




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 16, 2006 and examined and filed DECEMBER 13, 2006

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____