


**CORNER RECORD**

City of Novato

Document Number APN 146-250-81  
County of Marin, California

Brief Legal Description Parcel 2 of 11 PM 51



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey July 12, 2007

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

**Corner-** Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found nails along Hatch Road per 11 PM 51.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" Rebars and 3/4" IP with caps stamped "RCE 30465"

**SURVEYOR'S STATEMENT**

This corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 4, 2007

Signed [Signature] P.L.S. or R.C.E. No. 30465



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPTEMBER 7, 2007 and examined and filed OCTOBER 2, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



**County Surveyor's Comment** \_\_\_\_\_