


# CORNER RECORD

Document Number A.P. # 150-452-16

City of NOVATO County of MARIN, California

Brief Legal Description LOT 16, KADEN PARK UNIT 1, 12 R.M. 22



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey APRIL 26, 1993

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND 3/4" IRON PIPE WITH OUT CAP, SET CAP "LS6234"  
FOUND 1/2 " IRON PIPE WITHOUT CAP OR TAG. BOTH FOUND ACCEPTED IN POSITION.  
USED EXSTING STREET MONUMENTS AS BASTS FOR SETABLISHING CORNERS SET.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
BOTH FOUND CORNERS IN GOOD CONDITION.  
SET 1/2 " IRON PINS WITH CAP "LS 6234".

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 4, 1993 19\_\_.

Signed R. Walling L.S. or R.C.E. Number LS 6234

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 7 1993 and examined and filed B-7 1993.

Signed RDR Title DCS

County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

