


# CORNER RECORD

Document Number APN 150-522-08

City of Novato County of Marin, California

Brief Legal Description Lot 86 Map of Kaden Park Unit 2 (13RM13)



### CORNER TYPE

### COORDINATES (Optional)

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey April 22, 1998

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Reestablish the rear lot corners of Lot 86, Map of Kaden Park, Unit 2  
13 RM 13; from existing standard street monuments on Drakewood Place  
that are situate opposite Lots 86 and Lot 85; refer to sketch on  
reverse side for further detail.

A description of the physical condition of the monument as found and as set or reset:  
set one half inch rebar with PLS cap 5379 affixed to top of rebar and  
driven flush with existing natural surrounding grade

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on April 22 19 98


Signed *Douglas J. Scranton* L.S. or R.C.E. Number PLS 5379  
 renewal 6/30/2000



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 4 19 98 and examined  
 and filed MAY 4 19 95

Signed *John M. Wooley* Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

PREPARED BY DJ SCRANTON SURVEYING 845 OLIVE AVE. SUITE 208 NOVATO, CA 94945

