



JERRICO ASSOCIATES
 SUITE 27
 77 MARK DRIVE
 SAN RAFAEL, CA 94903


A.P. #160-104-05

6987

CORNER RECORD

1/1

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found standard subdivision monuments on Eagle Drive as shown in Marin Golf & Country Club Estates :- 10 R.M. 18


Novato

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

- (A) Set rebar and cap LS 3887.
- (B) Set nail & tag LS 3887 @ toe of rock wall.
- (C) Set hub and LS 3887 tag.
- (D) Set nail & tag LS 3887 @ toe of rock wall.
- (E) Set rebar and cap LS 3887. Fd. 3/4" I.P. (tag illegible).
- (F) Set rebar and cap LS 3887. Fd. 3/4" I.P. & RCE 14689
- (G) Set rebar and cap LS 3887. Fd. 3/4" I.P. & tack.
- (H) Set rebar and cap LS 3887. Fd. 1" I.P. & tack.
- (I) Set rebar and cap LS 3887. Fd. 1" I.P. & tack.
- (J) Set hub & tag LS 3887.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____


SKETCH: (Include reference tie or witness points, remarks and topo of area)



Marin Golf and Country Club Estates Unit 2
 R.M. Bk. 10-Pg. 18



THIS CORNER RECORD WAS REBUILT BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON July 7
 SIGNED: _____
 L.S. or R.C.E. No.: 3887



COUNTY SURVEYORS CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FOUND CORRECT BY _____ 7/24/96
 TITLE: _____
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET OF CALIFORNIA _____