



JERRICO ASSOCIATES

SUITE 27  
77 MARK DRIVE  
SAN RAFAEL, CA 94903


7371-1

# CORNER RECORD

Document Number 164-092-01

City of San Rafael County of Marin, California

Brief Legal Description Lot 470 Marinwood Unit 3-H 9 Maps 10



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey Sept. 7, 1999

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Standard subdivision monuments on Miller Creek Rd.  
per 9 Maps 10


A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

(A) (B) Set nail and tag LS 3887 on top of fence.  
(C) (D) Set #5 rebar and cap LS 3887

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyors' Act on Sept. 7 19 99.


Signed [Signature] L.S. or R.C.E. Number LS 3887



## COUNTY SURVEYOR'S STATEMENT



This Corner Record was received SEPTEMBER 17, 19 99 and examined  
and filed SEPTEMBER 20, 19 99.

Signed [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

SET NAIL & TAG ON TOP RUNNER OF LATTICE FENCE.  
TAG ELEV. 116.05 GRD. 111.75



FOUND STD. MONUMENT  
ELEV. DATUM IS ASSUMED.

CAP & TAGS SET ARE LS 3887

# SURVEY OF LOT 470

A.P. 164-092-01  
MARINWOOD UNIT 3-H 9 MAPS 10  
SAN RAFAEL CALIFORNIA  
AUGUST 1999

JERRICO ASSOC. 77 MARK DR., SAN RAFAEL, CA.

SET CORNERS : 9-7-99

S-7371-1