



JERRICO ASSOCIATES

7150


CORNER RECORD

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

Document Number 168-081-06

City of San Rafael County of Marin, California

Brief Legal Description Ptn. Lot 77 Lagunitas Tract Sub. 9 4 RM 81



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey July 19, 1995

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points along Westerly line of Lots 78, 79

(A) Found original 2"x3" and set tag LS 3887. 80, 81.

(B) Found original 2"x3" w/ 1"x3" marked '29'. Set #5 rebar at base of 2"x3".


A description of the physical condition of the monument as found and as set or reset:

(C) (D) Set #5 rebar and cap LS 3887.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 19 1995.

Signed [Signature] L.S. or R.C.E. Number LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-25 1995 and examined and filed 7-26 1995.

Signed [Signature] Title DES



County Surveyor's Comment _____

