


# CORNER RECORD

Document Number AP: 168-131-30

City of LAGUNITAS County of Marin State of California.

Brief Legal Description: LOT 45 LAGUNITAS TRACT #9 4 R.M. 81



**CORNER TYPE:**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 07/16/08

**COORDINATES:**

[Optional]  
N> \_\_\_\_\_  
E> \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev> \_\_\_\_\_

CORNER: ----- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

**FOUND 3/4" I P & TAG; NUMBER ILLEGIBLE**

A description of the physical condition of the monument as found and as set or reset:

**Original corners not found.  
Set points as shown on reverse.**



**SURVEYOR'S STATEMENT:**

The corner record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 16 2008


Signed: Douglas J. Matteson RCE# 18200

**COUNTY SURVEYORS STATEMENT:**

This corner record was received: 12-18 2008

and filed DECEMBER 30, 2008

Signed: [Signature] Title: COUNTY SURVEYOR



COUNTY SURVEYOR'S COMMENT \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

