


CORNER RECORD

Document Number A.P.N. 168-192-29

City of VICINITY OF LAGUNITAS County of MARIN, California

Brief Legal Description PARCEL 3 PER 12 P.M. 74



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 5-12-97

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

= SEE OVER =

A description of the physical condition of the monument as found and as set or reset:

= SEE OVER =

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 31 1997.


Signed David Contreras L.S. or R.C.E. Number LS 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 5 1997 and examined and filed AUGUST 5 1997.

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____

4 R.M. 97

SET 3/8" SPIKE @
S/4 EDGE OF HUB
TO HELP STABILIZE
HUB, S 39° 40' W, 0.11'
FROM FOUND POINT

BENARD INC
D.R. 85-37659

SET 3/8" SPIKE @
S/4 EDGE OF HUB
TO HELP STABILIZE
HUB, S 3° 32' W, 0.12'
FROM FOUND POINT

WHITE
PARCEL 2
2687 O.E. 475

A.P.N. 168-192-29
NESTLER
O.R. 97-032902

SET 3/8" SPIKE @ W/4
E OF HUB TO STAB.
L.I.Z.E., S 72° 11' W, 0.07'
FROM FOUND POINT

12 P.M. 74

SET 1/2" REBAR
& PLASTIC CAP
L.S. 5065
TYPICAL

STONE
O.R. 82-03521

