


CORNER RECORD

Document Number A.P.# 170-073-15#16

City of LAGUNITAS AREA

County of MARIN, California

Brief Legal Description N.E. COR 28 R. 99



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
RESET CORNER FROM POINTS FOUND ON
MY PREVIOUS RECORD OF SURVEY 28 R.S. 99
SEE SKETCH, A.P. 170-073-15#16

A description of the physical condition of the monument as found and as set or reset:
SET 1/2" RE BAR WITH PLASTIC CAP
STAMPED L.S. 2771

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 28 2000

Signed Paul B. Neese L.S. or R.C.E. Number L.S. 2771



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 11, 2000 and examined and filed AUGUST 15, 2000

Signed John M. Woolley Title DEPUTY



County Surveyor's Comment _____

