## **CORNER RECORD**

71-008 Agency Index Document Number AP#170-182-09 City of San Geronimo County of Marin , California Brief Legal Description Lot 15, 20 RM 100 **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation Meander Property Units Metric U.S. Survey Foot X Rancho Other Horizontal Datum **Epoch Date** Zone Date of Survey January 12, 2021 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8765(d) 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): An Iron Pipe and Plug (LS 3303, per 20 RM 100) was searched for and not found at all Property Corners which were set as shown hereon. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with 30465 the Professional Land Surveyors' Act on January 12, 2021 30465 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** 1-14-2021 This Corner Record was received and examined and filed P.L.S. or B.C.E. No. 9292 Signed

BPELSG-2016

**County Surveyor's Comment** 

Title

