

CORNER RECORD

Document Number A.P.# 175-031-01

City of SAN RAFAEL

County of MARIN, California

Brief Legal Description 10 R.M. 105

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9/29/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner: Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
ESTABLISHED THE SOUTHERLY PROPERTY LINE FOR LOT 52 PER 10 R.M. 105

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on SEPTEMBER 29 2003

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received OCTOBER 2, 2003



and examined and filed OCTOBER 10, 2003

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____





THE BASIS OF BEARING IS BETWEEN
TWO FOUND STREET MONUMENTS PER 10 R.M. 105

21°30'00\"
BASIS OF BEARING

TRELLIS DRIVE
60' R/W



CORNER RECORD
LOT 52 / 10 R.M. 105
SAN RAFAEL MARIN COUNTY CALIFORNIA

LAWRENCE P. DOYLE
LAND SURVEYOR/CIVIL ENGINEER
P.O. BOX 1609 MILL VALLEY CA 94942 (415-388-9585)

SCALE: 1" = 30'
DATE: 9/29/03

DRAWN BY: _____
SHEET 2 OF 2

DRAWING NO. 1198-03