



JERRICO ASSOCIATES

7186

CORNER RECORD


SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

Document Number 175-082-24

City of San Rafael

County of Marin, California

Brief Legal Description Parcel 'A' 6 O.S. 5 and 94-7233



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey APR 08 1996

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Monuments on Esmeyer Drive fronting
Lot 60 Terra Linda Unit 20 12 RM 32


A description of the physical condition of the monument as found and as set or reset: _____

- Found rebar and cap LS 4694/ accepted as corner.
- Found rebar and cap LS 4694
- Found tag LS 4694 in conc. drive
- Set drill-hole in conc. w/ Chisel cut.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 8 1996.

Signed [Signature] L.S. or P.C.E. Number 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 11 1996 and examined and filed 4-16 1996.

Signed [Signature] Title DCS



County Surveyor's Comment _____

