


CORNER RECORD

Document Number A.P. 176-032-05City of SAN ANSELMOCounty of MARIN, CaliforniaBrief Legal Description LOT 34 PER 8 R.M. 101

CORNER TYPE

COORDINATES (Optional)

Government Corner ☐Control ☐Meander ☐Property ☒Rancho ☐Other ☐Date of Survey 09/23/11

N. _____

E. _____

Zone _____

NAD27 ☐NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: _____

NGVD29 ☐NAVD88 ☐

Meas. Units: _____

Metric ☐Imperial ☐Corner- Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

ESTABLISHED THE EASTERLY AND WESTERLY LINES OF LOT 34 USING FOUND STREET MONUMENTSPER 8 R.M. 101 AND AS SHOWN ON SHEET 2.A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on SEPTEMBER 26, 2011Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

OCTOBER 17, 2011

and examined and filed

NOVEMBER 1, 2011Signed [Signature] P.L.S. or R.C.E. No. 7128Title COUNTY SURVEYOR

County Surveyor's Comment _____

MARTLING RD.

N23°16'30"E
16.00'

N66°43'30"W
81.83'

68.10'

S32°59'26"W
72.25'

LOT 33
RM 101
LOT 34

N31°25'32"E
154.23'


167.52'
72.24'

S44°48'00"W
149.823'

23.84'
90.34'

95.00'
N60°26'00"W

- FOUND STREET MONUMENT PER 8 R.M. 101
- SET 3/4" PIPE/PLUG L.S. 4694
- ∅ SET NAIL/TAG L.S. 4694 ON FENCE FOOTER



BASIS OF BEARING
THE BASIS OF BEARING IS BETWEEN TWO FOUND
STREET MONUMENTS PER 8 R.M. 101.

CORNER RECORD

LOT 34 PER 8 R.M. 101

SAN ANSELMO MARIN COUNTY CALIFORNIA

SCALE: 1" = 50'

DATE: 9/26/11

DRAWN BY:

SHEET 2 OF 2

LAWRENCE P. DOYLE

LAND SURVEYOR/CIVIL ENGINEER

100 HELENS LANE MILL VALLEY CA 94941 (415-388-9585)

DRAWING NO.

2136