## CORNER RECORD Agency Index\_\_\_\_\_

176-042-01 Document Number City of \_\_\_\_\_ County of \_\_\_\_ MARIN , California Brief Legal Description: LOT 49, "MAP OF SLEEPY HOLLOW KNOLLS UNIT TWO", FILED 10/21/1955, IN BOOK 8 OF MAPS AT PAGE 101, MARIN COUNTY RECORDERS OFFICE. **CORNER TYPE COORDINATES (Optional)** Government Corner [ ] Control [] Elevation: Meander Property M Units: Metric [ ] US Survey Foot X Rancho [] Other [ ] Horizontal Datum \_\_\_\_\_ Zone: Epoch Date 04/06/2021 Vertical Datum: Date of Survey Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8765(d) 8771 8773 Other: Left as found **X** Established Rebuilt Pre-Construction Corner/ Monument: Reestablished Found and tagged Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: X See sheet #2 for description(s): FOUND WELL MONUMENT WITH 1/8" PIN & TAG STAMPED RCE 3230 ON MARTLING ROAD; AND FOUND WELL MONUMENT WITH 1/8" PIN & NO TAG ON MARTLING ROAD: AND SET 3/4" REBAR & PLASTIC CAP "PLS 8080" AT MOST NORTHERLY CORNER OF LOT; AND SET 3/4" REBAR & PLASTIC CAP "PLS 8080" AT MOST NORTHWESTERLY CORNER OF LOT: AND SET 3/4" REBAR & PLASTIC CAP "PLS 8080" AT THE INTERSECTION DEFINED BY THE TWO COURSES N41°30'W & N74°30'W OF LOT 49; AS SHOWN ON PAGE 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with No. 8080 the Peofessional Land Surveyors' Act on \_\_\_\_\_\_ MAY 19, \_\_\_2021 EXP. 12-31-2021 Signed: COUNTY SURVEYOR'S STATEMENT The Corner Record was received MAY 17, 2021 and examined and filed JUNE 7, 2021 P.L.S. **PROP**NO. **817**6 PARK NO. 8176 Title: COUNTY SURVEYOR

DPW# 21-071

PAGE 1 OF 2

County Surveyor's Comment