## CORNER RECORD Document Number <u>APN 176-102-0</u>3 APN No. 1 7 6 - 1 0 2 - 0 3 MARIN \_\_\_\_\_, California SAN ANSELMO City of County of LOT 9 MAP OF SLEEPY HOLLOW HEIGHTS UNIT ONE (8 RM 37) Brief Legal Description \_\_\_ COORDINATES CORNER TYPE (Optional) Control $\square$ Government Corner Meander Property X Zone \_\_\_\_\_ Datum \_\_\_ Rancho 0ther Date of Survey 04/07/2011 Established 🔀 Reestablished Rebuilt | Corner -Left as found Found and tagged In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH \_\_\_\_ / REESTABLISH \_\_\_\_ the position of an existing monument PRIOR \_\_\_ / SUBSEQUENT \_\_\_\_ to street or highway reconstruction. (Use this portion only when applicable.) Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND MONUMENTS PER (8 RM 37), SEE PAGE 2 A description of the physical condition of the monument as found and as set or reset: SET IRON PIPE WITH PLASTIC KAP LS 7893, AND 2"x2" WOOD HUB WITH BRASS NAIL AND TAG LS 7893, AND 5/8" REBAR WITH PLASTIC KAP LS 7893, AS SHOWN. SEE PAGE 2. Surveyor's Comment This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_APRIL 13 \_\_\_20 11 \_\_. No. 7893 or R.C.E. Number LS 7893 County Surveyor's Comment This Corner Record was received APRIL 20, 20 11 and examined and filed MAY 18 20 11. \_\_\_\_\_ Title <u>County Surveyor</u> Signed County Surveyor's Comment\_\_\_\_\_

