


SHT. 1 of 2

A.P. #176-103-02

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set a 3/4" iron pipe with plastic plug "LS 3775" at the most Northerly corner of Lot 11, "Sleepy Hollow Unit 1", filed in Book 8 of Maps at Page 37, Marin County Records per said map.

A.P. # 176-103-02


J-1386 Gelsi-Medeot

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As shown


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____

SIGNED: _____
 L.S. or R.C.E. No. _____




COUNTY SURVEYOR'S CERTIFICATE
 NO. 18652
 THIS CORNER RECORD WAS RECEIVED May 31 1985
 AND EXAMINED AND FILED June 3 1985
 BY Charles E. Murphy
 CIVIL ENGINEER
 STATE OF CALIFORNIA
 COUNTY Surveyor

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒

CORNER RECORD

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 Set a 3/4" iron pipe with plastic plug "LS 3775" at the most Westerly corner of Lot 11, "Sleepy Hollow Unit 1", filed in Book 8 of Maps at Page 37, Marin County Records per said map.


A.P. # 176-103-02
 J-1386 Gelsi-Medeot

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

As shown



CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



THIS CORNER RECORD WAS PREPARED BY OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____

SIGNED _____
 L.S. or R.C.E. No. _____



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED May 31 1985
 AND EXAMINED AND FILED June 3 1985
 BY Charles E. Murphy
 COUNTY Surveyor

STATEMENT ON BACK OF SHEET

YES ☐ NO ☒