


# CORNER RECORD

Agency Index

Document Number

DPW# 19-127

APN 176-331-04

City of SAN ANSELMO County of MARIN, CaliforniaBrief Legal Description LOT 4 OF 15 RM 3, APN 176-331-04**CORNER TYPE****COORDINATES (Optional)**

- ☐ Government Corner ☐ Control  
☐ Meander ☒ Property  
☐ Rancho ☐ Other

Date of Survey October 16, 2019

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units ☐ Metric ☒ U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.:

☐ 8765(d)☐ 8771☐ 8773☐ Other:Corner/  
Monument:☐ Left as found☒ Established☐ Rebuilt☐ Pre-Construction☐ Found and tagged☐ Reestablished☐ Referenced☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet #2 for description(s):

POSITIONS ESTABLISHED FROM MONUMENTS PER 15 RM 3, AND FOUND 3/4" IRON PIPE MONUMENTS WITH CAP LS 6865 PER 33 RS 81. SET 1/2" IRON PIPE AND CAP LS 5290, AND NAIL & TAG, ON THE WESTERLY BOUNDARY LINE. SEE ATTACHED MAP FOR PARTICULARS.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on October 16, 2019

Signed

P.L.S. or R.C.E. No.

LS 5290**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received

October 21, 2019

and examined and filed

Nov. 13, 2019

Signed

P.L.S. or R.C.E. No.

9292

Title

DEPUTY C.S.

County Surveyor's Comment



