AUG 29 1988

Marin County Public Works

CORNER RECORD CALIFORNI MERIDIAN COUNTY OF MARIN OTHER [CONTROL BANCHO [] MEANDER [CORNER TYPE: GOVT. CORNER CORNER IDENTIFICATION - DATE OF VISIT -REESTABLISHED OBLITERATED CORNER REBUILT [7] FOUND AND TAGGED CORNER - LEFT AS FOUND PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR RESETABLISH PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED RESET STANDARD STREET MONUMENT STAMPED R.C.E. 18221 IN CENTER LINE OF INDIAN ROCK ROAD. SAN ANSELMO. AP.177-25 SECOND [] THIRD [] FIRST | CALIFORNIA COORDINATE SYSTEM ORDER: STATION . OTHER [STATIONS USED: NGS (USC & GS) COUNTY STATE 🗌 EASTINGS (X) _ NORTHINGS (Y) -ZONE ______ELEVATION _ SKETCH: (Include reference tie or witness points, remarks and topo of area) INDIAN ROCK LIMIT ONE <12 R.M.91> 42 39 33 4. 16.17. BEGGO: -FD. EXIST MON. CTYPS - RESET STO. ST. MON. SCALE 1"=100'

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY

DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

ON 70 50 57 26 19 88

SIGNED: 18 2 21

DOCUMENT No.

STATEMENT ON BACK OF SHEET

YES NO NO

OR OF ESSTON



