



JERRICO ASSOCIATES
 SUITE 27
 77 MARK DRIVE
 SAN RAFAEL, CA 94903

A.P. # 178-041-55

6692

CORNER RECORD

1/3

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH



⊙ Standard monumentation on Heather Way per. Las Colindas Unit 5
 8 R.M. 90 Marin County, California. Lot 155 (portion of)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Found drill hole in concrete. (Shown as plug and tag in 22 P.M. 63)

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON June 23 1987
 SIGNED: Edward Brunner
 L.S. or R.C.E. No. 3887



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED
 BY: Charles E. Murphy
 TITLE: Dep. Co. Surveyor

DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES NO



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

178-041-55

6692


CORNER RECORD

2/3

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard monumentation on Heather Way per. Las Colindas Unit 5
8 R.M. 90 Marin County, California. Lot 155 (portion of)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED




Set nail and L.S. 3887 in rock

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY EDWARD DWYER UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON June 23 1987

SIGNED: _____
L.S. or R.C.E. No.: _____

COUNTY Marin SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED 7-29 1987

BY: Charles E. Murphy
TITLE: Reg. Co. Surveyor

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO



JERRICO ASSOCIATES
 SUITE 27
 77 MARK DRIVE
 SAN RAFAEL, CA 94903

178-041-55

6692


CORNER RECORD

3/3

COUNTY OF Marin T. _____ R. _____ MERIDIAN _____ CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Standard monumentation on Heather Way per. Las Colindas Unit 5
 8 R.M. 90 Marin County, California. Lot 155 (portion of)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED




Found hub and tack. (Shown as 1" I.P. and tag in 22 P.M. 63)

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON June 27 No. 3887

SIGNED: _____
 L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED 20 1987
 BY: Charles E. Murphy
 TITLE: Dep. Co. Surveyor

DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET
 YES NO