CORNER RECORD				Document Number <u>179-191-01</u>				
City of San Raf	ael	•	Cou	nty of <u>Marir</u>	·			_, California
Brief Legal Description	Lot 35, Los	Ranchitos,	Book 2	Official	Surveys,	Page	116	
CORNER TYPE				COORDINATES (Optional)  N E NAD27 □ NAD83 □				
	Government Corner	☐ Control		Ë	NADOT O	NADOO		•
	Meaneder	☐ Property	鳘	NAD83 Epoc	:h	NAD83		
	Rancho  Date of Survey	Other 3/27/13	. 🗆	Elev Vert. Datum:	NGVD29  Metric	NAVD88	)	
Corner –	Left as found □	Found and tagged	□ ` Estab	lished 🗗 🛚 F	Reestablished	Re	ebuilt [	]
dentification and type of		· · · · · · · · · · · · · · · · · · ·						-
	monuments al					ositio	on ar	nd
used to ree	stablish the	Location o	of Lot 3	5, 2 0.S.	116			
A description of the phys								
					SONAL LAN	VO SEA		
	SURVE	YOR'S STATEMEN	11	ı				
	s prepared by me or un				The second	72	}	
the Land Surveyor's Ad Signed Missian	ton 4467. E. 70W P.L.	26, 2013 S-64RC.E. No. 72	237	_·	NO. 723 OF CAI	1100		
	COUNTY SU	IRVEYOR'S STATE	MENT	,	NALLAND	13		
This Corner Record wa	s received AUC	SUST 28, 2013	3			13/1		
	DOTOBER				RICHARD (SIMONITCI			
Signed Will	P.L.	S. o <del>r R.C.E</del> . No. <u>782</u>	2 1	- 115	No. 7821	Z X		
Title <u>DEPUTY</u>	CO. SURV				NO. 7621			
County Surveyor's Co	omment							
	-							-
								_
		*						

