


CORNER RECORD

Document Number

A.P.N. 179-191
A.P.N. 179-181
A.P.N. 179-241/242

City of VICINITY OF LOS RANCHITOS County of MARIN, California

Brief Legal Description PORTION OF 205.116



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey APRIL 4, 2005

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

3/4" IRON PIPE WITH TAG RCE 3230 WAS STRADDLED &
A STANDARD MONUMENT CASING WAS SET. THE IRON
PIPE WAS NOT SURVEYED FOR ITS CURRENT POSITION.
THIS WAS A JOINT EFFORT OF MARIN C.L.S.A. &
MARIN COUNTY ROAD CREW. (SEE OVER)

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 10 2005

Signed David Contreras P.L.S. or R.C.E. No. 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 28, 2005

and examined and filed JULY 27, 2005

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

