CORNER RECORD	Document Number 179 - 241 / 242
City of VICINITY OF LOS RANCHITOS	County of MARIN California
Brief Legal Description PORTION OF 2	2 0.5.116
CORNER TYPE	COORDINATES (Optional)
Government Corner ☐ Con Meander ☐ Pror	ZoneNAD27 □ NAD83 □
Rancho 🗆 Othe	NAD83 Epoch
Date of Survey APRIL 4	, 200S Vert. Datum: NGVD29 □ NAVD88 □ Meas. Units: Metric □ Imperial □
Corner – Left as found ☐ Found and tagged ☐	Established Reestablished Rebuilt
Identification and type of corner found: Evidence used to identify or 3/4" ROP PIPE WITH TAG RCE	procedure used to establish or reestablish the corner:
SET STANDARD MONUMENT CA	
PIPE IS ACCEPTED FOR POSITION	
THIS WAS A JOINT EFFORT	
	W. (SEE OVER)
A description of the physical condition of the monument as found are	nd as set or reset:
SURVEYOR'S STATEMENT	DAVID L.
This Corner Record was prepared by me or under my direction i	in conformance with
the Land Surveyor's Act on PRIL IDE JUNE 2	$25,2005$ EXP. § $30,07$ \Rightarrow
the Land Surveyor's Act on PRIL IDE JUNE & Signed Dwid Worteum P.L.S. or R.C.E. No. 5	5065 5065
	FE OF CALIFORNIA
COUNTY SURVEYOR'S STATEMENT	
This Corner Record was received JUNE 28, 2005	SED LAND SUS
and examined and filed JULY 27, 2005	
Signed P.L.S or R.C.E. No.	7128 (F) SEAL (R) S
Title LOUNTY SURVEYOR	Exp. 12-31-06 No. 7128 37
·	VICOT CALIFORNIA
County Surveyor's Comment	
-	
MARKET THE PARTY OF THE PARTY O	

