
CORNER RECORD	Doc	cument Number _	180-07
City of <u>Santa Vener</u>	hà Cou	inty of <u>Mari</u>	n, California
Brief Legal Description	Map of Gallinas Village	e unit six	
J.	.C. Oglesby R.C.E.	1953 7 RM 88	
CORNER TYPE	, , , , , , , , , , , , , , , , , , ,	Coordin (Optional	
Government Corner	Control	N	· · · · · · · · · · · · · · · · · · ·
Meander \square P	Property		
Rancho 🗆 O	Other 🔀	Zone	Datum
Date of Survey Sept. 2002	2	Elev.	
Corner - Left as found □	Found and tagged □	Established	Reestablished ⊠ Rebuilt □
Identification and type of corner found:	· Evidence used to identify	v or procedures used	to establish or reestablish the corner
Subdivision monuments on Vendola Drive at the intersection with LaBrea Way and Hacienda Way were referenced out prior to construction and later re-established.			
A description of the physical condition of the monument as found and as set or reset:			
Re-set Well Monuments in found location with brass disk punched RCE #15945.			
See Page Two			
SURVEYOR'S STATEMENT			
This Corner Record was prepared by me or under my direction in conformance with			
The Land Surveyor's Act on 11/06, 2003.			
Signed W. Edward	. *		159.45 Exp. 4/30/05
COUNTY SURVEYOR'S STATEMENT			
This Corner Record was received	NOVEMBER 1	∩ . ∩ ≥ and	examined
and filed NOVEMBER 20		<u> </u>	
			SED LAND SUR
\mathcal{L}	, Title <u>C</u>		VEYOR * Exp. 12/3/06/*
County Surveyor's Comments:			No. 7128
			G-CALIFO:
)			



CORNER RECORD

7 RM 88

NUTE ENGINEERING SAN RAFAEL, CA