

CORNER RECORD

Document Number 180-13

City of Santa Venefia

County of Marin, California

Brief Legal Description

Record of survey Mabry Way & western portion of Vendola Drive

DPW, Marin County 16 ROS 91

CORNER TYPE

Coordinates

(Optional)

Government Corner ☐

Control ☐

N. _____

Meander ☐

Property ☐

E. _____

Rancho ☐

Other ☒

Zone _____ Datum _____

Date of Survey Sept. 2002

Elev. _____

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedures used to establish or reestablish the corner:

Subdivision monument on Vendola Drive between Meadow Drive and Geneva Way was referenced out prior to construction and later re-established.

A description of the physical condition of the monument as found and as set or reset:

Re-set Well Monument in found location with brass disk punched RCE #15945.

See Page Two

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
The Land Surveyor's Act on 11/06, 2003.


Signed W. Edward Nute, R.C.E.



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 10, 03 and examined
and filed NOVEMBER 20, 03.

Signed _____, Title COUNTY SURVEYOR



County Surveyor's Comments: _____

