


# CORNER RECORD

Document Number A.P. #180-291-05City of SAN RAFAELCounty of MARIN, CaliforniaBrief Legal Description LANDS OF URICO, 3318 OR 108, AS SHOWN ON 20 P.M. 16  
A.P. 180-291-05

## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey \_\_\_\_\_

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

① FOUND HUB AND TAG R.E. 4560 AS SHOWN ON 20 P.M. 16  
RESET WITH 1/2 REBAR & CAP P.L.S. 4694

② REESTABLISHED ANGLE POINT OF PARCEL 2 20 PM 16  
WITH NAIL AND TAG P.L.S. 4694

A description of the physical condition of the monument as found and as set or reset:

① SET 1/2 REBAR & CAP P.L.S. 4694

② SET NAIL AND TAG P.L.S. 4694 IN CONCRETE  
DRAINAGE CHANNEL

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyors' Act on JULY 27 1998.


Signed Lawrence P. Doyle L.S. or R.C.E. Number P.L.S. 4694



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 14 1998 and examined  
and filed AUGUST 18 1998.

Signed John M. Woolley Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

**PARCEL 1**  
20 P.M. 16

A.P. 180-291-09

A.P. 180-291-05

**PARCEL 2**  
20 P.M. 16  
A.P. 180-291-10

A.P. 180-291-07

A.P. 180-291-08

**LEGEND**

- RESET FOUND HUB WITH REBAR & CAP. P.L.S. 4694
- SET TAG P.L.S. 4694 IN CHANNEL
- FOUND HUB & TAG L.S. 2535
- FOUND PIPE & TAG L.S. 2535

**BASIS OF BEARING**

BASIS OF BEARING IS N 56°05'00" E ACCORDING TO FOUND CORNERS PER 20 P.M. 16

SCALE: 1"=40'

