

CORNER RECORD


184-142-19

Document Number Lot 104, 10 RM 78

City of San Rafael

County of Marin, California

Brief Legal Description Lot #104, Marin Bay, Unit One 10 RM 78



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey 12/11/97

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Fd. Std. Street Monuments

A description of the physical condition of the monument as found and as set or reset:

Set new corners as shown on attached map (back)
1/2" iron bars with plastic cap embossed LS 5290

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Dec 18th 1997.

Signed David Hay L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 22 1997 and examined and filed December 23 1997.

Signed John M. Woolley Title Deputy



County Surveyor's Comment _____

