


CORNER RECORD

Document Number 184-143-04

City of San Rafael County of Marin, California

Brief Legal Description Lot 96 of 10 RM 78



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey 3/10/15

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard street monuments per 10 RM 78

A description of the physical condition of the monument as found and as set or reset:

Set 1/2 iron bar & cap embossed LS 5290

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 10, 2015

Signed David Harp L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 15, 2015 and examined

and filed APRIL 10, 2015
Signed David Simonitch Title DEPUTY



County Surveyor's Comment _____

