


CORNER RECORD

Document Number 185-095-01

City of San Rafael

County of Marin, California

Brief Legal Description Lot 11 of 12 RM 86



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8/15/16

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard Street Monuments per
subdivision map 12 RM 86

A description of the physical condition of the monument as found and as set or reset: _____

Set 1/2" iron bars and plastic caps LS 5290

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 08/16/16

Signed David Harp L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 19, 2016 and examined

and filed OCTOBER 20, 2016

Signed Richard G. Simonitch Title County Surveyor



County Surveyor's Comment _____

