CORNER RECORD	Docume	nt Number	AP# 185-111-19 , California	
City of San Rafael	County o	of Marin		
Brief Legal Description Lot 107, 12-RM-73				
Meander	PE Control Property Other	N E Zone NAD83 Epoch Elev	NAD27	NAD83
Date of Survey		Vert. Datum: Meas. Units:	NGVD29 Metric	NAVD88
Corner- Left as found 💢 Found and tagged 🔲	Established 🔀	Reestal	olished 🗌	Rebuilt
Identification and type of corner found: Evidence used to identification and Street Mons, per 12 RM 73.	•	lure used to e	stablish or reesta	ablish the corner:
A description of the physical condition of the monument as consisted of an Iron Pipe & Cap and a Nail & Tag set 10/23/2012. All Property Line points were set with R Drill Hole in AC Pavement and a Nail & Tag as show	on top of a wo Rebar & Cap. Pr	oden fence, operty Corn	per CR 185-11	11-18,
SURVEYOR'S STATEMENT				
This corner Record was prepared by me or under my direction in the Land Surveyor's Act on September 27, 2013 Signed P.L.S. or R.C.E. No. COUNTY SURVEYOR'S STATEM	. 30465		SHRED PROFESSION NO. 30463	ONAICE GINEER X
This Corner Record was received OCTOBER 2, 20 and examined and filed NOVEMBER 9th, 2 Signed P.L.S. or R.C.E. No. Title DEPUTY COUNTY SURVEYOR County Surveyor's Comment	013	 -	RICHARD SIMONITO	· 1 文
			NO. 782	(FORT)

