


CORNER RECORD

Document Number APN 185-201-16

City of SAN RAFAEL

County of MARIN, California

Brief Legal Description Parcel A 7 PM 87



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey OCTOBER 2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

STANDARD STREET WELL MONUMENTS IN THE CENTER OF DRIFTWOOD COURT WERE FOUND
IN GOOD CONDITION AND HELD AS BASIS FOR THIS SURVEY.
RECORD ANGLES AND DISTANCES WERE TURNED TO SET THE MOST SOUTHERLY
LOT CORNER AND THE EASEMENT ANGLE POINTS REQUESTED BY THE CLIENT.

A description and the physical condition of the monument as found and as set or reset:

A NAIL AND TAG SET IN A CONCRETE DRIVEWAY WAS FOUND IN GOOD CONDITION.
A 3/4" IRON PIPE WITH TAG RCE 12094 WAS SET AT THE MOST SOUTHERLY BOUNDARY
CORNER. 12" SPIKES WERE SET ALONG THE DRIVEWAY EASEMENT LINES.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on December 2010

Signed [Signature] P.L.S. of R.C.E. No. RCE 12094



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 5, 2011

and examined and filed JANUARY 12, 2011

Signed [Signature] P.L.S. of R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

