


CORNER RECORD

Document Number _____

City of San Rafael County of Marin, California

Brief Legal Description lot 89 (IIRM25)



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Ev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard City Monuments

A description of the physical condition of the monument as found and as set or reset:

Set 3/4" I.P. w/ Plastic Caps RCE 30465
See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Aug. 28 19 98

Signed Jay P. H. L.S. or R.C.E. Number RCE 30465



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 24 19 98 and examined and filed SEPTEMBER 25 19 98.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment _____



SCALE: 1"=50'

PEACOCK

L=183.05' Δ=29°58'00"

Lot 88
11 R.M. 25

S 70°33'00" W 125.00'
3' P.U.E.

Lot 89
11 R.M. 25

R=505.00' Δ=11°55'00" L=105.04'

R=380.00' Δ=11°55'00" L=79.03'

62.50' 62.50' 125.00'
N 82°28'00" E

Lot 90
11 R.M. 25

R=350.00'

L=390.95' Δ=64°00'00" L=207.90' Δ=34°02'00"

DRIVE

30' 30'

N 26°30'00" E 105.60'



LEGEND

- FOUND STREET MONUMENT PER 11 RM 25
- ✕ SET X-CUT
- SET 3/4 IP & CAP, RCE 30465