

CORNER RECORD

Agency Index

21-069


Document Number

APN 188-120-29

City of VICINITY OF BOLINAS

County of MARIN, California

Brief Legal Description LANDS DESCRIBED IN OFFICIAL RECORDS I.N. 2001-051596, MARIN COUNTY RECORDS



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey 12 MAY 2021

COORDINATES (Optional)

N. _____ E. _____
 Elevation _____
 Units Metric U.S. Survey Foot
 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____

- Complies with Public Resources Code §§8801-8819
- Complies with Public Resources Code §§8890-8902

PLS Act Ref: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction


Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on 12 MAY 2021

Signed [Signature] P.L.S. or R.C.E. No. 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 13, 2021 and examined and filed JUNE 2, 2021

Signed T. W. Park P.L.S. ~~08000~~ No. 8176

Title COUNTY SURVEYOR



County Surveyor's Comment _____



PREPARED BY
PHILLIP A. DANSKIN & ASSOCIATES
LAND SURVEYOR
SONOMA, CALIFORNIA
PHONE : (707) 938-2520

FOR : Louisa "Wiki" Newcomb
615 Paradise Valley Road
Bolinas, California
SURVEY No. 1169

GARDEN

WIRE FENCE

NEWCOMB, ET AL
I.N. 2001-51596

OSTERWEIS, TR
I.N. 2003-0133269

2004-M-54

SCALE : 1" = 60'

- Denotes set 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794"
- Denotes found 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794" per 2004-M-54

