

CORNER RECORD

DPW#19-008

Agency Index

APN 188-150-78 C


Document Number

I.N. 2016-026891

City of VICINITY BOLINAS

County of MARIN, California

Brief Legal Description LANDS DESCRIBED IN OFFICIAL RECORDS I.N. 2016-026891, MARIN COUNTY RECORDS



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey 31 JANUARY 2019

COORDINATES (Optional)

- N. _____ E. _____
- Elevation _____
- Units Metric U.S. Survey Foot
- Horizontal Datum _____
- Zone _____ Epoch Date _____
- Vertical Datum _____

- Complies with Public Resources Code §§8801-8819
- Complies with Public Resources Code §§8890-8902

PLS Act Ref: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction


Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on 31 JANUARY 2019

Signed [Signature] P.L.S. or R.C.E. No. 4794




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 6, 2019

and examined and filed APR. 10, 2019

Signed [Signature] P.L.S. or R.C.E. No. 9292

Title DEPUTY C.S.



County Surveyor's Comment _____



PREPARED BY
PHILLIP A. DANSKIN & ASSOCIATES
LAND SURVEYOR
SONOMA, CALIFORNIA
PHONE : (707) 938-2520

SURVEY No. 1023
FOR : Michael Light
46 Horseshoe Hill Road
Bolinas, California

SCALE : 1" = 60'

MARIN, TR.
I.N. 2018-037510

Found 3/4" I.D. iron pipe with plastic plug
"LS 6649 L.A. STEVENS" per Corner
Record 188-150-74. Accepted as corner

ICARUS TRUST
I.N. 2016-026891

PARCEL "B"
2 - P M - 67

VUILLE
I.N. 2015-028946


2015 - M - 104

POLHEMUS - VEZZANI
I.N. 96-060545

Found old 1/2" rebar. Perpetuated with
3/4" I.D. galvanized iron pipe with plastic
plug "DANSKIN PLS 4794" set over rebar.

- Denotes set 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794", unless noted otherwise
- ⊗ Denotes found 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794" per Corner Record dated 12 May 2017
- Denotes found 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794" per Corner Record dated 28 September 2015, unless noted otherwise

Found 3/4" I.D. iron pipe with
nail & tag "LS 2738" per
10-M-41. Accepted as corner



PARCEL TWO
I.N. 2001-0062313