
## CORNER RECORD

Agency Index CR 23-012 Document Number APN 191-172-13 , California Bolinas County of Marin City of Lot 3077 & Lot 3078 per Map of Bolinas Beach, 5 RM 44, MCR Brief Legal Description **CORNER TYPE** COORDINATES (Optional) E. Elevation Government Corner Control U.S. Survey Foot X Property Meander Units Metric Other Rancho Horizontal Datum Epoch Date Zone Date of Survey January 25, 2023 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8765(d) 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Post-Construction Found and tagged Reestablished Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found centerline monuments set by County per 10 OS 81, measured distance agrees with distance shown on 2017 Maps 49, held railroad spike at Iris Road. Found 3/4" iron pipes, PLS 7901 set per 2021 Maps 24. Set 5/8" rebar with yellow cap, PLS 7950 for lot corners, or references to lot corners as shown on Page 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with February 9, 2023 the Professional Land Surveyors' Act on 7950 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT February 20, 2023 This Corner Record was received February 21, 2023 and examined and filed P.L.S. No. <u>8176</u> Signed County Surveyor Title

**County Surveyor's Comment** 



BPELSG-2016 Page 2 of 2