


CORNER RECORD

Document Number 192-221-17

Community of Bolinas

County of Marin, California

Brief Legal Description Lots 124-133, 5 M 44



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 08/16/2016

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Overlook Drive centerline monuments as shown on 10 RS 81 and Corner Record 192-261-04.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on September 13, 2016.

Signed T. L. Park P.L.S. or R.C.E. No.: 8176



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 13, 2016 and examined
 and filed SEPTEMBER 13, 2016.

Signed Richard G. Simonitch P.L.S. or R.C.E. No.: P.L.S. 7821

Title County Surveyor

County Surveyor's Comment _____

