


CORNER RECORD

Document Number I.N. 1993-88363

City of Vicinity Bolinas

County of MARIN, California

Brief Legal Description Parcel One, 11-PM-36, Marin County Records



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- A Found 3/4" iron pipe with plastic plug "LS 2654"
- B Found 3/4" iron pipe with plastic plug "AAI LS 7901" per 2006-M 293
- C Found original 3/4" iron pipe with plastic plug "LS 2654" per 11-PM-36

A description of the physical condition of the monument as found and as set or reset: _____

- D Set 3/4" I.D. galvanized iron pipe with plastic plug "DANSKIN PLS 4794"
- E Set Railroad spike with "X" cut at easement line

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 2 October 2009

Signed [Signature] PLS or R.C.E. No. PLS 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 28, 2009

and examined and filed NOVEMBER 18, 2009

Signed [Signature] PLS or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____



SCALE: 1" = 40'



PARCEL 2
11-PM-36

WELSH
LN. 1993-88363

PARCEL 1
11-PM-36

DRIVEWAY

BRIGHTON AVENUE
70 RW

EASEMENT

SURVEY No. 952

FOR : Gregg Welsh
18 - 22 Brighton Ave.
Bolinas, California



PREPARED BY
PHILLIP A. DANSKIN & ASSOCIATES

LAND SURVEYOR
SONOMA, CALIFORNIA
PHONE : (707) 938-2520

