


CORNER RECORD

Document Number A.P. 195-104-18

City of STINSON BEACH

County of MARIN, California

Brief Legal Description 2009 M 136



CORNER TYPE COORDINATES (Optional)

Government Corner Control

Meander Property

Rancho Other

Date of Survey 1/16/2012

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED THE WESTERLY LINE OF LANDS OF OWEN USING POINTS FOUND ALONG THE WESTERLY LINE
OF LANDS OF OWEN PER 2009 M 136 AND AS SHOWN ON SHEET 2.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on JANUARY 16, 2012
 Signed Lawrence P Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 30, 2012
 and examined and filed FEBRUARY 29, 2012
 Signed [Signature] P.L.S. or R.C.E. No. 7128
 Title COUNTY SURVEYOR



County Surveyor's Comment _____

JOAQUIN PATIO

2009 M 136

N08°12'42"W
66.04'

BASIS OF BEARING

N28°28'30"E

27.53'

87.07'


24.24'

BASIS OF BEARING

THE BASIS OF BEARING IS N28°28'00"E
BETWEEN TWO FOUND 1/2" PIPES/PLUGS
L.S. 3890 PER 2009 M 136.

LEGEND

- FOUND 1/2" PIPE/PLUG
L.S. 3890
- SET 3/4" PIPE/PLUG
L.S. 4694



CORNER RECORD

2009 M 136

STINSON BEACH

MARIN COUNTY

CALIFORNIA

SCALE: 1" = 20'

DATE: 1/16/2012

DRAWN BY:

SHEET 2 OF 2

LAWRENCE P. DOYLE

LAND SURVEYOR/CIVIL ENGINEER

100 HELENS LANE MILL VALLEY CA 94941 (415-388-9585)

DRAWING NO.

2197