


CORNER RECORD

Document Number A.P. 195-104-18

City of STINSON BEACH

County of MARIN, California

Brief Legal Description 2009 M 136



CORNER TYPE COORDINATES (Optional)

Government Corner Control

Meander Property

Rancho Other

Date of Survey 1/16/2012

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED THE WESTERLY LINE OF LANDS OF OWEN USING POINTS FOUND ALONG THE WESTERLY LINE
OF LANDS OF OWEN PER 2009 M 136 AND AS SHOWN ON SHEET 2.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JANUARY 16, 2012

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 22, 2012

and examined and filed MARCH 14, 2012

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____



JOAQUIN PATIO

2009 M 136

N08°12'42"W
66.04'

BASIS OF BEARING

N28°28'00"E

27.53'

87.07'


24.24'

BASIS OF BEARING

THE BASIS OF BEARING IS N28°28'00"E
BETWEEN TWO FOUND 1/2" PIPES/PLUGS
L.S. 3890 PER 2009 M 136.

LEGEND

- FOUND 1/2" PIPE/PLUG
L.S. 3890
- SET 3/4" PIPE/PLUG
L.S. 4694



CORNER RECORD
2009 M 136

STINSON BEACH MARIN COUNTY CALIFORNIA

SCALE: 1" = 20'

DATE: 1/16/2012

DRAWN BY:
SHEET 2 OF 2

LAWRENCE P. DOYLE

LAND SURVEYOR/CIVIL ENGINEER
100 HELENS LANE MILL VALLEY CA 94941 (415-388-9585)

DRAWING NO.
2197