


CORNER RECORD

Document Number APN 195-107-09 & 10

City of Stinson Beach

County of Marin, California

Brief Legal Description Lots 57, 58, 59 & 119, "UPTON TRACT" SMAPS 61, AUG. 11, 1931



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 1/05/11

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 2" dia iron pipes as shown on page 2.


A description of the physical condition of the monument as found and as set or reset:

Set 1/2" dia x 3' rebars with brass tag marked "PLS 7779" at locations as shown on page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Jan 21, 2011

Signed Daniel J. Westover P.L.S or R.C.E. No. 7779



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 11, 2011

and examined and filed FEBRUARY 15, 2011

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

