CORNER RECORD

City of _____ County of _____


Agency Index
Document Number 199-202-11

DPU#21-047

Marin , California

Brief Legal Descrip	otion Northeast line of	the Lands of Bridge a	s shown on Record of Si	ırvey 2003 Maps 90, M.C.R.
	CORNER TYPE		COORDINATES (Optional)	
	Government Corner Meander Rancho Date of Survey	Control Property Other January 14, 2021	Horizontal Datum Zone Epoch Vertical Datum Complies with Public Re	U.S. Survey Foot Date Sources Code §§8801-8819 sources Code §§8890-8902
PLS Act Ref.:	× 8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found three 1/2" rebar tagged LS 5379 in good condition and record position as shown on Record of Survey 2003 Maps 90, Marin County Records and used to reestablish the northeast corner of 2003 Maps 90.				
This Corner Record was the Professional Land Signed	SURVEYOR'S ST as prepared by me or under Surveyors' Act on Janu Lach E. Janu		·	SCHAEL E. FORMER OF CALLED
	COUNTY SURVEYOR	'S STATEMENT		
This Corner Record was and examined and filed Signed T.k.	MAY 19, 2	P.L.S. 628-65. No.	8176	TRACY W. PARK NO. 8176

County Surveyor's Comment



FOUND 1/2" REBAR, LS 5793

SET 3" SPIKE WITH WASHER, LS7237

NOTES:

ALL DISTANCES SHOWN ARE IN FEET AND DECIMALS THEREOF.

ALL COURSES SHOWN HEREON ARE RECORD AND MEASURED PER RECORD OF SURVEY 2003 MAPS 90, MARIN COUNTY RECORDS.

ALL SURVEY TIES ARE PERPENDICULAR UNLESS OTHERWISE NOTED.

BASIS OF BEARINGS

N87°23'56"W BETWEEN TWO FOUND 1/2" REBAR, TAGGED LS 5379, AS SHOWN ON RECORD OF SURVEY FILED IN BOOK 2003 OF MAPS AT PAGE 90, MARIN COUNTY RECORDS.



2300 bethards drive, suite J

santa rosa • california 95405

p 707.542.8513 - f 707.542.1825

www.michaelfordinc.com