

CORNER RECORD


Agency Index DPW#20-063

Document Number APN 200-161-24

City of Mill Valley County of Marin, California

Brief Legal Description Lot 36 of Park Hill Unit 1, 11 Maps 61, Marin County Records

CORNER TYPE



- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey August 28, 2020

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found and held center line monuments on Erica Road. Set lot corners as shown. Northeast corner could not be set due to shallow subsurface obstruction. Set point on line 6.55 feet from true corner.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on August 29, 2020

Signed [Signature] P.L.S. or R.C.E. No. 7950



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 09/15/2020

and examined and filed 12/04/2020

Signed [Signature] P.L.S. or R.C.E. No. 9292

Title DEPUTY C.S.

County Surveyor's Comment



