


CORNER RECORD

Document Number _____

City of MILL VALLEY County of _____, California

Brief Legal Description LOTS 39 + 40 PARK HILL (11 RM 61)



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey APRIL 1998

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND STANDARD STREET MONUMENTS

A description of the physical condition of the monument as found and as set or reset:

SET NAIL AND BRASS TAGS, RCE 30465;
SET 3/4" IRON PIPE AND CAPS, RCE 30465;
SET 1/2" REBAR AND CAPS, RCE 30465;
SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on APRIL 9 1998.

Signed [Signature] L.S. or R.C.E. Number RCE 30465



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 15 1998 and examined and filed APRIL 16 1998.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

LEGEND

- FOUND STANDARD STREET MONUMENT
- SET NAIL TAG, RCE 30465
- ⊗ SET 3/4" I.P. & CAP, RCE 30465
- ✱ SET 1/2" REBAR & CAP, RCE 30465
- ③ LOT NO. PER MAP OF PARK HILL (11 RM 61)



SCALE: 1" = 50'

